



AMERICAN

FLOW CONTROL

THE RIGHT WAY

REMINDER SAFETY AND REMEDIATION NOTICE

On May 16, 2016, AMERICAN FLOW CONTROL (AMERICAN) notified its customers and distributors of a safety issue involving certain nozzles contained in American-Darling fire hydrants manufactured from 2006 through 2011. Later AMERICAN notified its customers and distributors through a SUPPLEMENTAL SAFETY AND REMEDIATION NOTICE that a very small number of hydrants shipped in early 2006 with a 2005 cast date on the hydrant barrel may also contain the nozzles subject to the Safety Notice. Please refer to both notices which are located on AMERICAN's website (http://www.american-usa.com/product_alerts/nozzles).

So far, AMERICAN has been very pleased with the results of the remediation campaign, and with the help of its valued customers and distributors, close to half of the affected hydrant nozzles have been replaced or are in the process of being replaced.

If you have not yet begun the remediation process, AMERICAN urges you to complete the inspection and replacement program as soon as possible.

Safety Hazard. Certain hose nozzles in the affected hydrants may develop cracks that, when the hydrant is pressurized, may cause the nozzle to separate from the hydrant upper barrel. The separation of a nozzle under pressure causes a loss of water pressure and renders the hydrant inoperable. Further, if nozzle separation under pressure occurs, parts, hoses or high pressure water may be projected from the hydrant, posing a serious safety risk.

Identification of Affected Hydrants and Nozzles. Affected hydrants can be identified by the year of manufacture, which appears in raised numbers on the hydrant upper barrel. The hose nozzles of affected hydrants bear a foundry mark of either the letter "L" or "S" on the interior surface of the nozzle, nearest the nozzle threads. Hose nozzles with the foundry mark "S" are subject to this notice and must be replaced. Pumper nozzles and hose nozzles with the foundry mark "L", or L and a numerical reference, such as "L5", are not subject to this notice and do not need to be replaced. Also excluded from this notice are American-Darling fire hydrants produced in 2005 and 2006 with Amlok nozzles.

If you believe that you may have an American-Darling fire hydrant subject to this notice, please contact AMERICAN Customer Service at 800-326-7082, Monday - Friday, 8 a.m. - 4:30 p.m. CT, or email AMERICAN at afcquestions@american-usa.com. Customer Service will direct you to an instructional video and instructions for identifying and replacing the nozzles; and provide information regarding reimbursable expenses, and accompanying forms and directions for submitting claims for reimbursement to AMERICAN. If you require the services of a contractor to inspect hydrants in your jurisdiction and replace the affected nozzles, AMERICAN has retained contractors who can perform these services. Customer Service can explain further and provide an order form requesting the information necessary to obtain contractor hydrant remediation services. You may also contact your AMERICAN sales representative for further information, or visit AMERICAN's website at www.american-usa.com.

AMERICAN Flow Control is a division of AMERICAN Cast Iron Pipe Company, whose goal for more than 100 years has been to provide the public with safe, dependable, high-quality products. In order to maintain the high standards for which our company is known, we are replacing all the hose nozzles in the fire hydrants described in this notice. At AMERICAN, we strive to do things "The Right Way." We proudly stand behind our products and will continue to deliver reliable products and excellent customer service, which are fundamental to our company's values. We appreciate your business.