


W67-250 and WB67-250

Ductile-Iron Pacer


These models with year markings of 1999 through 2004 are affected and are part of the program.



5-1/4" Ductile Iron Pacer - Models W67-250 and WB67-250
(Built from 1996 to Present)

W67 and WB67 Gray-Iron Pacer

These models are not affected nor part of the remediation program.



5-1/4" Gray Iron Pacer - Models WB67 and W67
(Built from 1967 to 1996)